

8月5日

久しぶりになってしまいましたが、こんな感じになりました。





この日は猛暑日。
たくさんの方が働い
ています。ありがと
うございます。

8月10日

A high-angle photograph of a construction site. The scene is dominated by a complex network of metal scaffolding and wooden formwork. A worker wearing a blue uniform and a white hard hat is visible in the upper-middle section, standing on a platform. The background shows more structural elements and a clear sky.

台風の日。
点検をして
くださっています。

異常なし。
また暑くなりそうです。



2学期始業式

8月27日



長～いクレーンでコンクリート
を流し込んでいます。

地面の下の部分は
こんな感じです



たくさんの区画が見えます。



8月30日



1つ1つの区画を
黄色い板で
仕切っています

A photograph of a construction site in a residential neighborhood. In the foreground, a red crawler crane is partially visible on the left. The ground is covered with various construction materials, including large stacks of yellow-painted wooden boards. Two workers in white protective suits and hard hats are working near the stacks. In the background, there are several houses with dark roofs and a grey metal fence. A yellow oval with Japanese text is overlaid on the image.

黄色い板は
こうやって
クレーンで吊り下げて
移動させます。



作業を
上から
見たところです